

Transmission Equipment >>Helix Conveyor



Helix Conveyor

Main applications: helix conveyor can operate continuously under the ambient temperature of 20 to +50 , temperature of transmitted materials should be lower than +200 and it must be installed with a maximum inclination of 20. It is mainly used to transmit powdery, grainy, and small materials. It has been widely used in building materials, metallurgy, electricity, chemistry, light industry, and food industry.